



Mary Meyer Certificate of Compliance

- I. This certificate covers Mary Meyer item: Lulujo 70% viscose bamboo 30% cotton Mini muslin
- II. LJ208, LJ209, LJ210
- II. This product is certified to meet the following CPSC safety regulations:
Lead content : CPSIA Sec. 101
Phthalates CPSIA §108
Small parts and sharp edges 16CFR 1501
- III. This product was imported by:
Mary Meyer Corp.
Route 30
Townshend, VT 05353 USA
Tel (+852)-3580-0773
- IV. Testing and compliance records are maintained by:
- | | |
|---|---|
| Hong Kong:
Mary Meyer (Hong Kong) Limited
Room 804, Tung Che Commercial Centre
246 Des Voeux Rd. West
Hong Kong, S.A.R. Peoples' Republic of China
Tel: (+852)-2915-2506
Email: compliance@marymeyer.com
Attn: Jeffrey Blauner | USA:
Mary Meyer Corp.
P.O. Box 275
Townshend, VT 05353
USA
Tel: (802)-365-7793
email: compliance@marymeyer.com
Attn: Gail Ames |
|---|---|
- V. This product was manufactured in:
Ningbo , China March 2017
- VI. The product covered by this certificate was tested for compliance:
- VII. Third party testing was conducted by:

Mary Meyer Corp.
P.O. Box 275, Route 30
Townshend, VT 05353 USA
Tel: (802)-365-7793 Fax: (802)-365-4233