

Mary Meyer Certificate of Compliance

- I. This certificate covers Mary Meyer item: MM43100 Itsy Glitzy Fawn Ring Rattle
- II. This product is certified to meet the following CPSC safety regulations:

ASTM F963 + 16 CFR Flammability Test
16 CFR 1303 Total Lead Content
ASTM F963 + 16 CFR Physical and Mechanical Test
ASTM F 963 Soluble Heavy Metal Content
Total Lead in substrate per CPSIA 2008 (H.R. 4040)
Total Phthalates Content Test per CPSIA 2008 (H.R. 4040)

III. This product was imported by:

Mary Meyer Corp. Route 30 Townshend, VT 05353 USA Tel (+852)-3580-0773

IV. Testing and compliance records are maintained by:

Hong Kong:

Mary Meyer (Hong Kong) Limited Room 804, Tung Che Commercial Centre 246 Des Voeux Rd. West Hong Kong, S.A.R. Peoples' Republic of China

Tel: (+852)-2915-2506 Email: compliance@marymeyer.com

Attn: Jeffrey Blauner

V. This product was manufactured in:

GuangAn City, Linshui County, Sichuan province, Peoples' Republic of China March 2018

VI. The product covered by this certificate was tested for compliance:

Hong Kong, S.A.R., Peoples' Republic of China

August 2017 Component testing:

Eyes testing (Heavy Metals): May 2017 Label testing (Heavy Metals): May 2017

Other: Other: Other:

VII. Third party testing was conducted by:

UL VS Hong Kong Limited 16-17/F, Tower B, Regent Centre 63 Wo Yi Hop Road, Kwai Chung New Territories, Hong Kong S.A.R., Peoples' Republic of China (+852)-2423-3092 USA: Mary Meyer Corp. P.O. Box 275 Townshend, VT 05353 USA Tel: (802)-365-7793

email: compliance@marymeyer.com

Attn: Gail Ames

Mary Meyer Corp. P.O. Box 275, Route 30 Townshend, VT 05353 USA Tel: (802)-365-7793 Fax: (802)-365-4233