

Mary Meyer Certificate of Compliance

I. This certificate covers Mary Meyer item: MM43100 Itsy Glitzy Fawn Ring Rattle

II. This product is certified to meet the following CPSC safety regulations: ASTM F963 + 16 CFR Flammability Test 16 CFR 1303 Total Lead Content ASTM F963 + 16 CFR Physical and Mechanical Test ASTM F 963 Soluble Heavy Metal Content Total Lead in substrate per CPSIA 2008 (H.R. 4040) Total Phthalates Content Test per CPSIA 2008 (H.R. 4040)

- III. This product was imported by: Mary Meyer Corp. Route 30 Townshend, VT 05353 USA Tel (+852)-3580-0773
- IV. Testing and compliance records are maintained by: Hong Kong: Mary Meyer (Hong Kong) Limited Room 804, Tung Che Commercial Centre 246 Des Voeux Rd. West Hong Kong, S.A.R. Peoples' Republic of China Tel: (+852)-2915-2506 Email: compliance@marymeyer.com Attn: Jeffrey Blauner

- USA: Mary Meyer Corp. P.O. Box 275 Townshend, VT 05353 USA Tel: (802)-365-7793 email: compliance@marymeyer.com Attn: Gail Ames
- V. This product was manufactured in: GuangAn City, Linshui County, Sichuan province, Peoples' Republic of China April 2018
- VI. The product covered by this certificate was tested for compliance: Hong Kong, S.A.R., Peoples' Republic of China August 2017 Component testing: Eyes testing (Heavy Metals): May 2017 Label testing (Heavy Metals): May 2017 Other: Other:

Other:

Other:

VII. Third party testing was conducted by: UL VS Hong Kong Limited 16-17/F, Tower B, Regent Centre 63 Wo Yi Hop Road, Kwai Chung New Territories, Hong Kong S.A.R., Peoples' Republic of China (+852)-2423-3092

> Mary Meyer Corp. P.O. Box 275, Route 30 Townshend, VT 05353 USA Tel: (802)-365-7793 Fax: (802)-365-4233