

## Mary Meyer Certificate of Compliance

- I. This certificate covers Mary Meyer item: MM 43130 Tingo Flamingo Rattle
- II. This product is certified to meet the following CPSC safety regulations: ASTM F963 + 16 CFR Flammability Test 16 CFR 1303 Total Lead Content ASTM F963 + 16 CFR Physical and Mechanical Test ASTM F 963 Soluble Heavy Metal Content Total Lead in substrate per CPSIA 2008 (H.R. 4040) Total Phthalates Content Test per CPSIA 2008 (H.R. 4040)
- III. This product was imported by: Mary Meyer Corp. Route 30 Townshend, VT 05353 USA Tel (+852)-3580-0773
- IV. Testing and compliance records are maintained by: Hong Kong: Mary Meyer (Hong Kong) Limited Room 804, Tung Che Commercial Centre 246 Des Voeux Rd. West Hong Kong, S.A.R. Peoples' Republic of China Tel: (+852)-2915-2506 Email: compliance@marymeyer.com Attn: Jeffrey Blauner
- V. This product was manufactured in: Nanjing, Jiangsu Province, Peoples' Republic of China December 2020
- VI. The product covered by this certificate was tested for compliance: Hong Kong, S.A.R., Peoples' Republic of China December 2020 Component testing Eyes testing (Heavy Metals): January 2020 Label testing (Heavy Metals): January 2020 Other: Other: Other: Other:
  VII. Third party testing was conducted by:
- VII. Third party testing was conducted QIMA Testing (HK) Limited 3/F Liven House No. 61 – 63 King Yip Street Kwun Tong, Kowloon Hong Kong Tel: (852)3185 8000

Mary Meyer Corp. P.O. Box 275, Route 30 Townshend, VT 05353 USA Tel: (802)-365-7793 Fax: (802)-365-4233

USA: Mary Meyer Corp. P.O. Box 275 Townshend, VT 05353 USA Tel: (802)-365-7793 email: compliance@marymeyer.com Attn: Gail Ames