

## Mary Meyer Certificate of Compliance

I. This certificate covers Mary Meyer item: MM43240 Afrique Alligator Teether Rattle

 II. Citation to each CPSC product safety regulation to which this product is being certified: ASTM F963 - 17 CFR Flammability Test (16 CFR 1500.44) 16 CFR 1303 Total Lead Content (CPSIA) ASTM F963 - 17 CFR Physical and Mechanical Test (CPSIA) ASTM F963 - 17 Soluble Heavy Metal Content (CPSIA) Total Lead in substrate per CPSIA 2008 (H.R. 4040) Total Phthalates Content Test per CPSIA 2008 (H.R. 4040)

III. This product was imported by: Mary Meyer Corp. Route 30

Townshend, VT 05353 USA Tel (+852)-3580-0773

- IV. Testing and compliance records are maintained by: Hong Kong: Mary Meyer (Hong Kong) Limited Room 804, Tung Che Commercial Centre 246 Des Voeux Rd. West Hong Kong, S.A.R. Peoples' Republic of China Tel: (+852)-2915-2506 Email: compliance@marymeyer.com Attn: Jeffrey Blauner
- V. This product was manufactured in: Huaying City, Sichuan province, Peoples' Republic of China March 2024
- VI. The product covered by this certificate was tested for compliance: Hong Kong, S.A.R., Peoples' Republic of China Component testing: November 2023

Eyes testing (Heavy Metals): May 2023 Label testing (Heavy Metals): May 2023 Other: Other: Other: Other:

VII. Third party testing was conducted by: QIMA Testing (HK) Limited 3/F Liven House No. 61 – 63 King Yip Street Kwun Tong Kowloon Hong Kong Tel: (852)3185 8000

> Mary Meyer Corp. P.O. Box 275, Route 30 Townshend, VT 05353 USA Tel: (802)-365-7793 Fax: (802)-365-4233

USA: Mary Meyer Corp. P.O. Box 275 Townshend, VT 05353 USA Tel: (802)-365-7793 email: compliance@marymeyer.com Attn: Gail Ames

Mary Meyer Corp. P.O. Box 275, Route 30 Townshend, VT 05353 USA Tel: (802)-365-7793 Fax: (802)-365-4233